ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0037, W0022, W0033	NA	Muneshwaranagara
Segment No.	**Total Length (m)**	
5/C-W0037/S121445	213.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	55.22	77.623837	13.124865	77.624341	13.124799	4th A Cross	End
2	102.76	77.624429	13.125744	77.624356	13.124818	4th cross	Govt School Road
3	55.84	77.623878	13.125414	77.623841	13.124910	Govt School	4th A Cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Muneshwara nagara and surrounding area in ward No. 05 Jakkur	9700000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021		
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC Drain CulvertsCC Road	005-21-000019
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/18/2021-22	14/07/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
14/07/2021	13/07/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Umesh N		0.00
Phone No.	**E-Mail ID**	
9036184395		

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0037, W0022, W0033

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ದ್ಯಾವರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ದ್ಯಾವರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Scanned by CamScanner

Field Inspection Details

Number of Trees

0

Any Other Information

Name

mahantesh kumar

Date of Inspection

30/09/2021

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	30/09/2021	30/10/2021	As proposed
SE	Vijay Kumar Haridas	30/09/2021	30/10/2021	Forwarded
EE	Mohan Das H T	30/09/2021	30/10/2021	Approved
AEE	B S Sridhar	30/09/2021	30/10/2021	Approved
AE	Mahantesh Kumar Y N	30/09/2021	30/10/2021	Mob Verification Done
AE	Mahantesh Kumar Y N	30/09/2021	30/10/2021	For Mob Verification

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0037, W0022, W0033

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mananagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0247, W0235	4th Crs, NA	Shivapura
Segment No.	**Total Length (m)**	
5/C-W0247/S122032	137.64	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	137.64	77.622283	13.119434	77.622093	13.118204	Main Road	End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Muneshwara nagara and surrounding area in ward No. 05 Jakkur	9700000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021		
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC Drain Culverts	005-21-000019
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/18/2021-21	14/07/2021	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
14/07/2021	13/07/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Umesh N		0.00
Phone No.	**E-Mail ID**	
9036184395		

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ ಯಲಹಂಕ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Zone: YELAHANKA Ward No: 5 Ward Name: Jakkuru Street ID: W0247, W0235

Date: 30/09/2021 Time: 15:19:32 RH20210930151932

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		mahantesh kumar
Date of Inspection	**Remarks**	
30/09/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	30/09/2021	01/11/2021	As proposed
SE	Vijay Kumar Haridas	30/09/2021	01/11/2021	Forwarded
EE	Mohan Das H T	30/09/2021	01/11/2021	Approved
AEE	B S Sridhar	30/09/2021	01/11/2021	Approved
AE	Mahantesh Kumar	30/09/2021	01/11/2021	Mob Verification Done
AE	Mahantesh Kumar Y N	30/09/2021	30/10/2021	For Mob Verification

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Scanned by CamScanner